

Bug Fix (V3.03.02 – 1/2)



No.	Category	Feature	TFS No.	Behavior Details
1	Setup	Insert Jig	143805	PX registered jigs may not be displayed in the CAM jig insert list. This issue is fixed.
2	Weld Edge	Select	153434	When creating an SR process for a point of a slit setback pattern, the setback pattern or virtual weld line may not be recognized correctly. This issue is fixed.
3	Weld Edge	Weld Condition	153443	The setback pattern of a bent corner (vertex) of SR process may not be recognized. This issue is fixed.
4	Setup	Auto Table Sequence	151527	When performing an automatic calculation with TOA enabled for grouped weld edges, the result is output in which the robot cannot reach the target position. This issue is fixed.
5	Weld Edge	Weld Condition	140029	When applying welding conditions, hidden parts are displayed. This issue is fixed.
6	Weld Edge	Select	152497	When selecting an edge, an exception error may occur. This issue is fixed.
7	Setup	Auto Table Sequence	153792	When performing Auto Table Sequence calculation with the direction reversal of weld edges enabled, an exception error may occur. This issue is fixed.
8	Setup	Copy With Welds	141402	The property notation of a setup created by Copy With Welds is incorrect. This issue is fixed.
9	Weld Edge	Select	153839	When creating a laser spot, the reference plane may be drawn in the wrong position. This issue is fixed.

Bug Fix (V3.03.02 – 2/2)



No.	Category	Feature	TFS No.	Behavior Details
10	Weld Edge	Select	141337	An exception error would occur when grouping welding edges for which no reference plane was set. This issue is fixed.
11	Robot Path	Space Point	153791	Even if the robot path is set to nothing, the robot path is displayed when an space point is inserted. This issue is fixed.
12	Setup	Layout	157446	The product position of a setup created by copying Copy With Welds cannot be changed. This issue is fixed.

It has No new fixed bug in this version.

Bug Fix (V3.03.04 – 1/1)



No.	Category	Feature	TFS No.	Behavior Details
1	Setup	Insert Jig	162514	The registered jig added in PX may not be displayed in the CAM jig insert list. This issue is fixed.